

## SB, BEARING HOUSING, K760, 2017-07

### SYMPTOM/DESCRIPTION

The M10 spindle bolt on K760 is phased in during 2017.

The Bearing Housing will be able to order with M8 OR M10 threads in the spindle shaft.

P/N	Thread
581 35 17-09	M10
581 35 17-10	M8



For more information regarding the change of spindle bolt please read SB: **B170007A**.